

# DELTA SCHOOL DISTRICT ASBESTOS MANAGEMENT PROGRAM

Building: Burnsview Secondary

Date: December 12, 2011

Surveyor: James McArthur (ACM Environmental Corporation)

Room No.	AREA CONTAINS WRAPPED OR NON-FRIABLE ASBESTOS, DO NOT DISTURB								AREA CONTAMINATED WITH ASBESTOS, SPECIAL ENTRY PROCEDURES REQUIRED								Comments
	1	2	3	4	5	6	7	8	1	2	3	4	5	6	7	8	
All					X												Yellow/Brown Duct Mastic & Grey/Green Duct Mastic
108A						X											12" Olive Vinyl Floor Tile with Dark and White Streaks (<1%) (library workroom)
108B						X											12" Olive Vinyl Floor Tile with Dark and White Streaks (<1%) (library storage)
129						X											12" Olive Vinyl Floor Tile with Dark and White Streaks (<1%) (stage)
129A						X											12" Olive Vinyl Floor Tile with Dark and White Streaks (<1%) (stage dressing room)
140			X														Drywall Taping Compound (boys washroom east of library)
143A			X														Drywall Taping Compound (north boiler room)
143C			X														Drywall Taping Compound (electrical vault)
153			X														Drywall Taping Compound (boys washroom south of foods room)
169			X														Drywall Taping Compound (boys washroom north of gym)
177						X											12" Olive Vinyl Floor Tile with Dark and White Streaks (<1%) (custodial room)
180						X											12" Olive Vinyl Floor Tile with Dark and White Streaks (<1%) (hub room)

**Legend**

- |   |   |   |   |
|---|---|---|---|
| 1 | ASBESTOS IN ABOVE-CEILING SPACES            | 5 | ASBESTOS ON VISIBLE PIPING AND/OR DUCTING |
| 2 | ASBESTOS ON CEILING SURFACES                | 6 | ASBESTOS IN FLOORING MATERIAL             |
| 3 | ASBESTOS ON WALLS (DRYWALL OR CEMENT BOARD) | 7 | ASBESTOS IN FIRE DOORS                    |
| 4 | ASBESTOS IN BELOW-FLOOR AREAS               | 8 | ASBESTOS IN WINDOW PUTTY                  |