

DELTA SCHOOL DISTRICT ASBESTOS MANAGEMENT PROGRAM

Building: Cliff Drive Elementary

Date: July 31, 2011

Barry O'Regan (ACM Environmental Corporation)

Room No.	AREA CONTAINS WRAPPED OR NON-FRIABLE ASBESTOS, DO NOT DISTURB								AREA CONTAMINATED WITH ASBESTOS, SPECIAL ENTRY PROCEDURES REQUIRED								Comments
	1	2	3	4	5	6	7	8	1	2	3	4	5	6	7	8	
All		X	X														Drywall Joint Compound (all rooms excluding 129, 226, 145, 132)
All		X	X														Drywall Joint Compound (all unexposed finished drywall sections, e.g. carpet covered drywall)
101C						X											Vinyl Floor Tile (medical)
109						X											Vinyl Floor Tile (library - under carpet)
111						X											Vinyl Floor Tile (north end daycare)
120A						X											Vinyl Floor Tile (storage under main entry stairs)
125A						X											Vinyl Floor Tile (north end storage)
128						X											Vinyl Floor Tile (hub room/storage)
138						X											Vinyl Floor Tile (<1%) (gym storage)
137						X											Vinyl Floor Tile (<1%) (kitchen)
132						X											Vinyl Floor Tile (copy room)

Legend

- 1 ASBESTOS IN ABOVE-CEILING SPACES
- 2 ASBESTOS ON CEILING SURFACES
- 3 ASBESTOS ON WALLS (DRYWALL OR CEMENT BOARD)
- 4 ASBESTOS IN BELOW-FLOOR AREAS

- 5 ASBESTOS ON VISIBLE PIPING AND/OR DUCTING
- 6 ASBESTOS IN FLOORING MATERIAL
- 7 ASBESTOS IN FIRE DOORS
- 8 ASBESTOS IN WINDOW PUTTY