

# DELTA SCHOOL DISTRICT ASBESTOS MANAGEMENT PROGRAM

Building: Delta Manor Education Centre

Date: September 12, 2005

Surveyor: Barry O'Regan (ACM Environmental Corporation)

Room No.	AREA CONTAINS WRAPPED OR NON-FRIABLE ASBESTOS, DO NOT DISTURB								AREA CONTAMINATED WITH ASBESTOS, SPECIAL ENTRY PROCEDURES REQUIRED								Comments	
	1	2	3	4	5	6	7	8	1	2	3	4	5	6	7	8		
All			X															Plaster Materials Areas (except Gym Kitchen 132)
103						X												Beige Vinyl Floor Tile with Thin Brown Streaks (<1%) (classroom)
115						X												Pale Orange-Pink Vinyl Floor Tile (<1%) (custodial east of library)
128						X												Beige Vinyl Floor Tile with Brown and Grey Streaks (<1%) (girls change storage)
130						X												Beige Vinyl Floor Tile with Brown and Grey Streaks (<1%) (gym storage)
140			X															Stucco Filler (<1%) (boiler room)

- Legend**
- 1 ASBESTOS IN ABOVE-CEILING SPACES
  - 2 ASBESTOS ON CEILING SURFACES
  - 3 ASBESTOS ON WALLS (DRYWALL OR CEMENT BOARD)
  - 4 ASBESTOS IN BELOW-FLOOR AREAS

- 5 ASBESTOS ON VISIBLE PIPING AND/OR DUCTING
- 6 ASBESTOS IN FLOORING MATERIAL
- 7 ASBESTOS IN FIRE DOORS
- 8 ASBESTOS IN WINDOW PUTTY