

DELTA SCHOOL DISTRICT ASBESTOS MANAGEMENT PROGRAM

Building: North Delta Secondary

Date: January 10, 2005

Surveyor: James McArthur (ACM Environmental Corporation)

Room No.	AREA CONTAINS WRAPPED OR NON-FRIABLE ASBESTOS, DO NOT DISTURB								AREA CONTAMINATED WITH ASBESTOS, SPECIAL ENTRY PROCEDURES REQUIRED								Comments
	1	2	3	4	5	6	7	8	1	2	3	4	5	6	7	8	
All					X												Silver Duct Mastic (all areas pre-2001)
All		X															2x4 Ceiling Tiles with small notches and pinholes (all areas pre-2001)
All			X														Original Drywall Joint Compound (all areas pre-2001)
0003						X											9" Beige Vinyl Floor Tile with Orange Streaks (book room)
0019A						X											9" Beige Vinyl Floor Tile with Orange Streaks (hub room)
1521						X											12" Beige Vinyl Floor Tile with Orange Streaks (<1%) (theatre south corridor)
1522						X											12" Beige Vinyl Floor Tile with Orange Streaks (<1%) (stage large storage room)
1526						X											12" Beige Vinyl Floor Tile with Orange Streaks (<1%) (theatre north corridor)
1653						X											12" Beige Vinyl Floor Tile with Orange Streaks (auto shop storage room)
1654						X											12" Beige Vinyl Floor Tile with Orange Streaks (auto shop storage room)
1655						X											12" Beige Vinyl Floor Tile with Orange Streaks (auto shop office)

Legend

- | | | | |
|---|---|---|---|
| 1 | ASBESTOS IN ABOVE-CEILING SPACES | 5 | ASBESTOS ON VISIBLE PIPING AND/OR DUCTING |
| 2 | ASBESTOS ON CEILING SURFACES | 6 | ASBESTOS IN FLOORING MATERIAL |
| 3 | ASBESTOS ON WALLS (DRYWALL OR CEMENT BOARD) | 7 | ASBESTOS IN FIRE DOORS |
| 4 | ASBESTOS IN BELOW-FLOOR AREAS | 8 | ASBESTOS IN WINDOW PUTTY |